The Nuclear Waste Problem

Jack Devanney Center for Tankship Excellence, USA, djw1@c4tx.org

There are two two keys to understanding the nuclear waste problem:

1. The quantities involved.

2. The difference between gamma and alpha radiation.

Figure 1 shows the dry cask storage facility for Connecticut Yankee near Haddam Neck on the Connecticut River.



Figure 1: Connecticut Yankee Dry Storage Facility

Connecticut Yankee (CY) was a 619 MWe pressurized water reactor that ran for 28 years between 1968 and 1996. During that time the plant produced 110 million MWh. There are 43 casks on a concrete

pad, 78 feet by 228 feet.¹ These casks contain about 1020 tons of spent fuel. The fuel is surrounded by 3.5 inches of steel and then 21 inches of reinforced concrete. Each cask weighs about 126 tons, of which about 25 tons is the spent fuel itself. Each cask also has internal passages for natural draft circulation to remove the heat produced by the spent fuel's radioactive decay. These show up in Figure 1 as the rectangular slots at the bottom and top of each cask.

If Connecticut Yankee had been a coal plant, it would have produced between 3,000,000 and 6,000,000 tons of toxic ash in its operating life, not to mention 110 million tons of CO2. If we attempted to store this ash on the CY fuel cask pad, we would have a column of ash about 7000 feet high.

Almost all the material in these casks falls into one of three categories:

- 1. Spent uranium.
- 2. Fission products.
- 3. Transuranics.

Spent uranium is not radioactive. By weight it represents about 96% of the spent fuel.

Fission products are the result of the nuclear fuel breaking into two pieces. They represent about 3% of the spent fuel. Most fission products decay by emitting electrons and photons. These photons or gamma rays are what makes spent fuel so difficult and expensive to handle. The electrons have very little penetrating power. Few can penetrate the outer layer of skin. But a gamma ray can easily penetrate all the way through a human body. Gamma rays are the reason the casks in Figure 1 are as big as they are. Fission product decay is relatively rapid. The spent fuel in the casks in Figure 1 was stored underwater for at least five years during which time the fission product decay heat dropped by a factor of 400. If the fission products were to stay in the casks for 500 years, the gamma radiation from the fission products would be down to background level.

Some of the neutrons in the reactor do not result in fission but are absorbed by the fuel transmuting the uranium into still heavier elements, such as neptunium, plutonium, etc known as transuranics (TRU). By weight the TRU represent about 1% of the spent fuel. Transuranics decay by emitting electrons and alpha particles. As we have seen, electrons have little penetrating power. Alpha particles have still less. Most alpha particles cannot penetrate a piece of paper. In order for alpha particles to do any damage, they must be ingested or inhaled.

Transuranic decay tends to be very slow with some important TRU isotopes having half-lives of the order of 100,000 years. TRU's also can be quite valuable. Some such as Pu-238 can be used to power deep space probes. Others are either fissile or fertile and can be processed into excellent nuclear fuel, although currently this is not economic, in part because the fission product decay makes handling the spent fuel so difficult.

These facts suggest an obvious solution to the nuclear waste problem.

- Keep the spent fuel in dry casks for say 100 years. At this point, the fission product decay will be down by another factor of ten. In 2012, the USA consumed 3826 million kWh. If all this power had been produced by Connecticut Yankees at the not very good capacity factor CY averaged over 28 years, we would need just under 1000 Connecticut Yankees. The CY pad is just over 0.4 acres. If the US were all nuclear, every 28 years the nation would have to set aside roughly 400 acres for dry cask storage.
- 2. Transfer the 100 year old fuel to fewer, smaller dry casks.
- 3. Repeat for 2 or 3 cycles. Now the FP gamma decay is down to near background levels. and the spent fuel can be handled with only alpha and electron protection basically bunny suits or glove

 $^{^{1}40}$ of the casks contain spent fuel. Three contain other material that did not meet the Class C standards for landfill disposal. This material will decay faster than the spent fuel.

boxes.

- 4. At this point, it will be quite cheap to separate the non-radioactive uranium from the rest of the fuel by fluoride volatility, the same process that was used in enriching the fuel. This will reduce the amount of waste be more than a factor of twenty. The remaining 40 tons could easily be stored in a single cask. A facility the size of the CY pad could handle the TRU waste from 40 Connecticut Yankees. The spent uranium could be fed to a breeder reactor or re-enrichment; but, even in the unlikely event this is not economic, the uranium presents no disposal problem.
- 5. However, given the low level of gamma radiation, it will almost certainly pay to separate the valuable TRU from the decayed fission products. The fission products some of which, such as platinum, are also valuable could then be put in a Low Level Waste landfill. We are now down to 10 tons of TRU. 10 tons of TRU is a cube about 2.6 ft on a side.
- 6. This cube could be dumped down a borehole or better sent to a WIPP. A single borehole could take a 1000 Connecticut Yankees operating for 30 years. But a more intelligent approach would be to separate out the extremely valuable isotopes such as Pu-238 and Am-241 and then burn the rest in a fast reactor. Due to processing losses, we will not be able to fission all the TRU, but we will get at least another order of magnitude reduction in waste. The material in Figure 1 is now down to a cube about 1 ft on a side. This material, dangerous only if ingested or inhaled, can go to deep geologic disposal.

The solution to the nuclear waste problem is both obvious and cheap.